#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors:

U. Reichert et al.

Attorney Docket No: BOEH124931

Patent No:

US 7,205,685 B2

Art Unit: 2834 / Confirmation No.: 2040

Issued:

April 17, 2007

Title:

SOLENOID PLUNGER SYSTEM WITH AN ADJUSTABLE MAGNETIC FLUX

#### REQUEST FOR CERTIFICATE OF CORRECTION

Seattle, Washington 98101

ATTN: CERTIFICATE OF CORRECTION BRANCH COMMISSIONER FOR PATENTS:

Enclosed is a Certificate of Correction, Form PTO 1050, for the above-identified U.S. Letters Patent. The errors in the printed patent listed on the enclosed form occurred at the corresponding locations in the application file listed below:

Column,	Line	Page,	Line
8 (Claim 15,	20 line 3)	9 (Claim 25, (Amendment	
8 (Claim 16,	23 line 3)	9 (Claim 24, (Amendment	

Since the Certificate of Correction is necessitated by Patent and Trademark Office errors, no fee is required.

Respectfully submitted,

CHRISTENSEN O'CONNOR

JOHNSON KINI

Kevan L. Morgan Registration No. 42,015

Direct Dial No. 206.695.1712

KLM/lac

LAW OFFICES OF CHRISTENSEN O'CONNOR JOHNSON KINDNESSPAR 1420 Frith Avenue Suite 2800 Seattle, Washington 98101 206.682,8100

### UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO. : US 7,205,685 B2
DATED : April 17, 2007
INVENTOR(S) : U. Reichert et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN LINE ERROR

8	20	"plunger arranged." should readplunger arranged
(Claim 15,	line 3)	between the solenoid plunger and the first shell
8 (Claim 16,	23 line 3)	delete "between the solenoid plunger and the first shell."